



कार्यालय नगर निगम मथुरा-वृन्दावन, मथुरा

पत्रांक : ०१ / नि०वि०का० / न०नि०म०वृ०, (वृन्दावन जोन) / 2021-22

दिनांक: 22/07/2021

Building Safety Certificate

Certified that **HPDS BALIKA VIDYA MANDIR RAMANRETI VINDAVAN MATHURA (U.P.)** Comprises of ground floor/first floor/Second floor floor/ Third floor owned/occupied at **RAMANRETI VINDAVAN MATHURA (U.P.)** has complied with the Building Bye Laws in accordance with rule of state/UT, and incorporate the provision of building safety as specified in National Building code 2005, School safety policy 2016 and as amended thereafter and has been verified by the officer on **18-07-2021** (date of inspection) in the presence of **Dr. Anjoo Sood** Principal of **HPDS BALIKA VIDYA MANDIR RAMANRETI VINDAVAN MATHURA (U.P.)**

The Structure of the school building is in good condition Brick walls are constructed with cement mortar and roofs are of R.C.C slab. All the rooms are well ventilated and airy. Floors are constructed with first class material. School Building falls in seismic Zone-III Structure of school building (i.e. foundation, column, beam, etc.) and that the above said building / premises is safe and fit for running school up to Senior Secondary. The building is made according to safety norms.

Attested
Ajay
Principal
Hanuman Prasad Dhanuka
Saraswati Balika Vidya Mandir
Senior Secondary School
Vrindavan

अवर अभियन्ता
नगर निगम मथुरा-वृन्दावन
मथुरा (वृन्दावन)